

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5278	DATE	Feb. 16. 2023
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain emergency exit doors of heavy duty buses, due to inappropriate fitting structure of the shaft of the indoor operating handle and the drive lever, there are some where the fitting allowance is insufficient. Therefore, the emergency exit door may not open due to idling when the handle is operated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QTG-RU1ASCA	[HINO Selega]	2017	296
2TG-RU1ASDA		2017~2018	226
QRG-RU1ESBA		2017	187
2RG-RU1ESDA		2017~2018	195
2DG-RU2AHDA		2017~2018	69
2KG-RU2AHDA			
LDG-RU8JHBA		2017	134
SDG-RU8JHBA			
QQG-RU1ASBR		2017	1
		TOTAL	