

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5279	DATE	February 16 ,2023
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain emergency exit doors of heavy duty buses, due to inappropriate fitting structure of the shaft of the indoor operating handle and the drive lever, there are some where the fitting allowance is insufficient. Therefore, the emergency exit door may not open due to idling when the handle is operated.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QTG-RU1ASCJ	[ISUZU GALA]	2017	310
2TG-RU1ASDJ		2017-2018	138
QRG-RU1ESBJ		2017	100
2RG-RU1ESDJ		2017-2018	72
2DG-RU2AHDJ□ 2KG-RU2AHDJ		2017	25
LDG-RU8JHBJ□ SDG-RU8JHBJ		2017	124
		TOTAL	769