

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5280	DATE	Feb. 16. 2023
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The timing chain may be improperly put on the exhaust cam shaft sprocket, due to the improper assembling process of the engine.</p> <p>The timing chain may fail to drive the exhaust camshaft and cause the engine stalling, if the vehicle is being used continuously with the above condition.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5BD-DA17V	EVERY	2022	1	
		TOTAL	1	