

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5282	DATE	Feb.16.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In an exhaust manifold, due to insufficient strength of a pipe portion of the exhaust manifold, there is a possibility that a crack may occur on the pipe if the vehicle is operated repeatedly under high-load condition, rising excessively the pipe surface temperature, and at certain engine speed such as on an uphill. If the vehicle is continuously operated, the vehicle emission does not meet a certain emission standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-NTP10 6AA-NTP10	[JPN TAXI]	2017-2020	23,586
		TOTAL	23,586