

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5286	DATE	February 24 ,2023
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In some engines for light-duty trucks, the clearance between the vacuum pump coupling and the camshaft is large. Consequently, if the engines continue to be used under such a condition, the fitting point of the coupling and the camshaft abnormally wears, which can break down the coupling and thus lead to the vacuum pump's malfunction with the break warning lamp and the vacuum warning lamp on and clutch and break operations becoming heavier. In addition, cam rotor's breakage and VVT (variable valve timing) mechanism's phase shift can deteriorate the engines' startability, which might, in the worst case, cause the engines to stall.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-NHR88A□ 2RG-NHR88AN	[ELF]	2019-2022	3,667
2RG-NHS88A□ 2RG-NHS88AN		2019-2022	2,009
2RG-NJR88A□ 2RG-NJR88AD□ 2RG-NJR88AN□ 2RG-NJR88N□ 2SG-NJR88AN		2019-2022	12,184
2RG-NJS88A□ 2RG-NJS88AN		2019-2022	1,796
2PG-NKR88N□ 2PG-NKR88R□ 2RG-NKR88A□ 2RG-NKR88AD□ 2RG-NKR88AN□ 2RG-NKR88AR□ 2RG-NKR88N□ 2RG-NKR88R		2019-2022	22,628
2PG-NKR88YN□ 2RG-NKR88YN		2018-2022	1,907
2PG-NKS88A□ 2PG-NKS88AD□ 2PG-NKS88AN□ 2RG-NKS88A□ 2RG-NKS88AN		2019-2022	3,498

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2RG-NLR88AN□ 2RG-NLR88AR□ 2RG-NLR88N□ 2SG-NLR88AN	[ELF]	2018-2022	11,932	
2RG-NLS88AN□ 2RG-NLS88AR		2019-2022	802	
2PG-NMR88N□ 2PG-NMR88R□ 2RG-NMR88AN□ 2RG-NMR88AR□ 2RG-NMR88N□ 2RG-NMR88R□ 2SG-NMR88AN□ 2SG-NMR88N		2018-2022	11,395	
2PG-NMS88AN□ 2PG-NMS88AR□ 2RG-NMS88AN□ 2RG-NMS88AR		2019-2022	1,874	
2RG-NNR88AN□ 2RG-NNR88AR□ 2RG-NNR88N		2019-2022	764	
2RG-NNS88AN		2019-2022	73	
2PG-NPR88AN□ 2PG-NPR88AR□ 2PG-NPR88N□ 2RG-NPR88AN□ 2RG-NPR88AR□ 2RG-NPR88N□ 2SG-NPR88AN		2018-2022	22,581	
2PG-NPR88YN□ 2RG-NPR88YN		2018-2022	12,320	
2PG-NPS88AN□ 2PG-NPS88AR□ 2RG-NPS88AN□ 2RG-NPS88AR		2019-2022	2,044	
2RG-AHR88A□ 2RG-AHR88AN		[ATLAS]	2019-2022	1,692
2RG-AHS88A□ 2RG-AHS88AN			2019-2022	548
2RG-AJR88A□ 2RG-AJR88AD□ 2RG-AJR88AN			2021-2022	171
2RG-AJS88A□ 2RG-AJS88AN			2021-2022	33

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-AKR88A□ 2RG-AKR88AD□ 2RG-AKR88AN□ 2RG-AKR88AR□ 2RG-AKR88N□ 2RG-AKR88R	[ATLAS]	2021-2022	146
2PG-AKS88AD□ 2PG-AKS88AN□ 2RG-AKS88A□ 2RG-AKS88AN		2021-2022	28
2RG-ALR88AN□ 2RG-ALR88AR□ 2RG-ALR88N		2021-2022	32
2RG-ALS88AN□ 2RG-ALS88AR		2021-2022	5
2RG-AMR88AN□ 2RG-AMR88AR□ 2RG-AMR88N□ 2RG-AMR88R		2021-2022	95
2PG-AMS88AN□ 2RG-AMS88AN□ 2RG-AMS88AR		2021-2022	12
2RG-ANR88AR		2021-2022	8
2RG-APR88AN□ 2RG-APR88AR		2021-2022	175
2RG-APR88YN		2021-2022	11
2PG-APS88AN□ 2RG-APS88AR		2021-2022	4
2RG-LHR88A□ 2RG-LHR88AN		[TITAN]	2019-2022
2RG-LHS88A□ 2RG-LHS88AN	2019-2022		317
2RG-LJR88A□ 2RG-LJR88AD□ 2RG-LJR88AN□ 2RG-LJR88N	2019-2022		509
2RG-LJS88A□ 2RG-LJS88AN	2019-2022		59
2RG-LKR88A□ 2RG-LKR88AD□ 2RG-LKR88AN□ 2RG-LKR88AR□ 2RG-LKR88N□ 2RG-LKR88R	2019-2022		559

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-LKR88YN	[TITAN]	2020-2021	2	
2PG-LKS88AD□ 2PG-LKS88AN□ 2RG-LKS88A□ 2RG-LKS88AN		2019-2022	80	
2RG-LLR88AN□ 2RG-LLR88AR□ 2RG-LLR88N		2019-2022	184	
2RG-LLS88AR		2020-2022	9	
2RG-LMR88AN□ 2RG-LMR88AR□ 2RG-LMR88N□ 2RG-LMR88R		2019-2022	137	
2RG-LMS88AN□ 2RG-LMS88AR		2019-2021	8	
2RG-LNR88AN□ 2RG-LNR88AR		2019-2022	50	
2RG-LNS88AN		2019-2022	3	
2RG-LPR88AN□ 2RG-LPR88AR		2019-2022	300	
2RG-LPR88YN		2019-2022	101	
2PG-LPS88AN□ 2PG-LPS88AR□ 2RG-LPS88AN□ 2RG-LPS88AR		2019-2022	27	
		TOTAL	118,014	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF □ VEHICLE
Vacuum Pump	8-97501641-0 8-97501641-1 8-98343477-1	2021-2022	9
4JZ1 ENGINE	8-97546935-0 8-97546943-0 8-97546950-0 8-97546957-0 8-97546975-0 8-97546979-0 8-97546980-0 8-97546997-0 8-97821961-0 8-97821974-0 8-97821992-0	2021-2022	19
TOTAL			28