VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5289	DATE	Feb.28 2023
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty and medium-duty touring buses, the mounting hardware holding the resin cover of the ceiling air conditioning unit may rust due to improper antirust treatment. If the vehicle continues to be used in this condition, the fixing force of these mounting hardware lowers as the rust progresses. In the worst case, a strong crosswind, etc. could lift the cover and break the fixing sections, causing the cover to fall off the ceiling air conditioning unit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-MS96JP	「FUSO AERO ACE」	2007~2010	425
PDG-MM96FH		2008~2011	259
LDG-MM96FH		2011~2012	7
LKG-MS96VP		2010~2012	282
QDG-MM96FH		2012~2015	30
QDG-MM97FH		2014~2017	71
SDG-MM96FH		2011~2012	28
TDG-MM96FH		2012~2014	131
TDG-MM97FH		2014~2017	338
QRG-MS96VP		2012~2017	1,361
QTG-MS96VP		$2015\sim2017$	1,568
PDG-AM96FH		2008~2011	13
BKG-AS96JP	「SPACEARROW A」	2007~2010	23
LKG-AS96VP		2010~2011	8
		TOTAL	4,544