

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5285	DATE	March 2, 2023
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the integrated body control computer in the fuse block, an internal short circuit may occur due to the improper manufacturing process of the capacitor. Therefore, if the fuse is continuously used as it is, the fuse may blow out and the lights may not be turned on or the engine may stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA850S	MOVE CANBUS	2022-2023	123
5BA-LA860S			20
5AA-A202S	ROCKY	2023	35
5AA-A202A	RAIZE		65
		TOTAL	243