

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5292	DATE	March 15, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In battery operated forklift wipers, the length of the spring attached to the wiper arm is incorrect, causing the wiper to press hard against the windshield. For this reason, if continued to be used as it is, the wiper may stop halfway and stop functioning. In addition, due to improper design of the wiper motor cover, there is a risk that water might enter through the gaps and corrode inside of the motor, causing the wiper to stop functioning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-M299	FE25-2 FE30-2	2021-2022	81
ZAF-M300	FE30-2	2022	1
TOTAL			82