

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5293	DATE	March 15, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p><1> The side cover fixing pin may not normally fit in the latch due to improper structure of engine side cover on excavators or loaders. If the machine is continued to be used as it is, the pin may come off the latch due to operation vibration, and the side cover may fall off the machine in the worst case.</p> <p><2> The plate and bracket which are fixing the hydraulic tube between the work equipment pump and control valve piping on excavators or loaders may break due to their low strength and engine vibration. If it occurs, the hydraulic tube is released. If the machine is used as it is, the welds of the hydraulic tube may crack and the hydraulic oil may leak badly, and as a result the work equipment and other components may malfunction.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	「WA470-10 」	2019-2023	37
TOTAL			37