

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5301	DATE	2023/3/31
MANUFACTURER	TOHO CAR CORPORATION		
DESCRIPTION OF DEFECT	In a trailer with a lift axle function, the clamping plate securing the air spring for lifting the lift device was broken, and parts of the lift device were found to have fallen off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TC25F9N2S	—	2022	5
TC28H8B2	TC28H8B2	2021~2022	27
TC29G0N2S	—	2021	3
TC29H6N2S	—	2022	2
TC30H8N2S	—	2021	1
TC31F5N3S	—	2021~2022	5
TC31F6N3S	—	2020~2022	10
TC32F5N3S	—	2021	2
TC32F6N3S	—	2022	1
TC33F5N3S	—	2020	1
TC34F5N3S	—	2020	2
TC35F6N3S	—	2021~2022	9
TC36G3N3S	—	2022	3
TC36G7N3S	—	2020~2022	9
TC36G8N3S	—	2022	3
TC36G9N3S	—	2021	1
TC36H1C33	TC36H1C33	2021	1
TC36H1C34	TC36H1C34	2020~2022	2
TC36H1N3	TC36H1N3	2020~2022	74
TC36H1N3S	—	2022	5
TE36H2C3	TE36H2C3	2020~2022	20
TE36H8N3S	—	2022	4
TF26E5N2S	—	2022	3
TF28H7B2	TF28H7B2	2020	11
TF28H8C21	TF28H8C21	2020~2022	29
TF31K1C2	TF31K1C2	2021	1
TF36E8N3S	—	2022	1
TF36F0N3S	—	2022	3
TF36G0N3S	—	2021	2

TF36G4N3S	—	2021	1
TF36G8N3S	—	2021	1
TF36H0N3S	—	2021	1
TF36H2C3	TF36H2C3	2020~2023	303
TF36H2N3S	—	2021~2022	9
TF36H3N3S	—	2021	1
TF36H5N3S	—	2022	2
TF36H8N3S	—	2022	1
TH28H7B2	TH28H7B2	2021	6
TH28H7N2	TH28H7N2	2022	8
TH30H4N2S	—	2021	6
TH30H8N2S	—	2020~2022	20
TH31J7N2S	—	2022	6
TH36H1N3S	—	2021	4
TH36H4N3S	—	2022	1
TH36H5N3S	—	2021	1
TH36H8N3S	—	2020~2021	3
TJ36H2N3S	—	2021	1
TT24F2N2S	—	2021~2022	23
TT24F5N2S	—	2022	1
TT26F4N2S	—	2021~2022	3
TT28J9C2	TT28J9C2	2021~2022	36
TT30G6N2S	—	2021~2022	3
DNPT E241A	DNPT E241A	2021~2022	23
DNPT F341A	DNPT F341A	2021~2022	22
54 types in total	54 models in total	Overall range of production period 2020-2023	726