VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5302	DATE	5. April. 2023	
MANUFACTURER	YAMAHA MOTOR CO., LTD.			
DESCRIPTION OF DEFECT	For police vehicles, the wiring instructions for the connecting section of the right-side siren are not indicated properly in the drawing, so the wires are connected in the opposite direction. Because of this, the sound volume of the siren may not meet the safety standards.			

TYPE	COMMERCIAL		MODEL	NUMBER OF
	NAME	YEAR RECALLED		VEHICLE
2BL-RP25J	FJR1300AP	2019~2021		126
			TOTAL	126

The applicable range of vehicles on which the replacement parts were installed.

TYPE	COMMERCIAL		MODEL	NUMBER OF
	NAME	YEAR RECALLED		VEHICLE
2BL-RP25J	FJR1300AP	2021~2022		2
			TOTAL	2