

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5303	DATE	5. April. 2023
MANUFACTURER	YAMAHA MOTOR ENGINEERING CO., LTD.		
DESCRIPTION OF DEFECT	For firefighting motorcycles, the wiring instructions for the connecting section of the right-side siren are not indicated properly in the drawing, so the wires are connected in the opposite direction. Because of this, the sound volume of the siren may not meet the safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-DG31J	SEROW XT250	2019~2022	16
		TOTAL	16

Something shipped as a replacement repair part and for which the assembled vehicle cannot be identified.

PART NAME	PART NUMBER	MODEL YEAR PART	NUMBER OF PART
SPEAKER ASSEMBLY,2	BK5-88170-01	2020~2022	3
		TOTAL	3

Vehicles with replacement repair parts assembled shall be subject to the same improvement.