

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5305	DATE	Apr.6.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the starter, due to an improper tightening requirement of through bolts, there is a possibility that the bolts may loosen and misalignment of components may occur over time, resulting in reducing starter output. In this condition, the starter cannot start the engine, and if starter is repeatedly engaged to try to start the engine, the starter can overheat, in the worst case, vehicle fire could occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NSP170G	[SIENTA]	2015-2017	123,946
DBA-NSP172G			4,965
DBA-NSP141	[PORTE] [SPADE]		57,178
DBA-NRE161	[COROLLA AXIO]		18,327
DBA-NRE161G	[COROLLA FIELDER]		30,371
			TOTAL