

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5309	DATE	24.APL.2023
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	Some of the lubricating holes in the transmission lubricating hole of the agricultural chemical spraying vehicle have inappropriate lubricating hole display marks. The main mission display mark is affixed to the submission lubrication port, and the submission display mark is affixed to the main mission lubrication port. Therefore, when lubricating, an amount of oil that is less than the required amount may be lubricated. If you try to drive in this state, the internal parts may be damaged and you may not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA	SSA-E502DX	2021~2023	130
	SSA-E502DX-1		
		TOTAL	130