

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5310	DATE	April.24. 2023
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	On dump trucks equipped with tail lamp protection cover at the rear of vehicle, there are cases that the installation position of rear underrun protection device is inappropriate. Due to the prescribed condition, the horizontal distance from the flat surface of rear underrun protection device to the rear end of vehicle exceeds the standard, and does not comply to safety regulations for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HX	SUPER GREAT	2021~2022	16
2PG-CXZ77CT	GIGA	2022	1
2KG-CXZ77CT		2021	1
		TOTAL	18