

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5316	DATE	April 26, 2023
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the fuel devices of internal-combustion engine forklift and shovel loader vehicles, because of improper design of fuel pipe for returning excessive fuel to tank, there are fuel pipes that may not fulfill enough strengths. In case of starting and stopping the engine repeatedly with current condition, there is a possibility that it may cause the fuel pipe to crack and lead to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A8FDL18	TOYOTA GENE0	2015 - 2022	2,015
YDN-A8FDL25		2015 - 2022	8,351
YDN-A8FDL30		2015 - 2022	910
YDN-A8FD18		2015 - 2022	143
YDN-A8FD25		2014 - 2022	897
YDN-A8FDJ35		2014 - 2022	1,004
YDN-A6SD7	TOYOTA SHOVEL LOADER	2018	1
YDN-A6SD12		2015 - 2022	12
YDN-A6SD15		2017 - 2022	9
		TOTAL	13,342