

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5322	DATE	May.25.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On a urea SCR system in the exhaust gas prevention module, due to improper processing and fixing heater cable for urea liquid delivery pipe, there is a possibility that the heater cable could be damaged by driving vibration etc. If this were to occur, a warning light will illuminate and the urea SCR system will be suspended. This could cause the exhaust gas does not meet the criteria.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3DF-GDH201V 3DF-GDH201K	[HIACE]	2021-2022	17,214	diesel engine vehicles
3DF-GDH206V 3DF-GDH206K 3DF-GDH206K “kai”(modified)			18,235	
3DF-GDH211K			1,283	
3DF-GDH221K			546	
3DF-GDH226K			1,024	
3DF-GDH223B			486	
3DF-GDH201M			[BONGO BRAUNY VAN]	
3DF-GDH206M	138			
		TOTAL	39,010	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDF-GDH201V	[HIACE] [REGIUS ACE]	2018-2019	3
QDF-GDH206V		2017-2020	9
QDF-GDH211K		2020	1
QDF-GDH226K			1
		TOTAL	14

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
UREA TUBE ASSY W/HEATER	77840-V3010	2021-2022	77
	77840-V3020		4
		TOTAL	81