

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5321	DATE	May 26, 2023
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In the impeller (resin impeller) of the fuel pump, the resin density becomes low due to improper molding conditions, which may cause the impeller to swell and get deformed by the fuel.</p> <p>As a result, the impeller may interfere with the pump case, which may cause the fuel pump to malfunction and in the worst case, the engine may stall while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2019	12,888
DBA-LA160S			3,155
DBA-LA250S	CAST		9,753
DBA-LA260S			1,930
5BA-LA350S	Mira e:s		20,576
5BA-LA360S			3,820
DBA-LA550S	Mira TOCOT		3,767
DBA-LA560S			702
DBA-LA600S	TANTO		16,510
DBA-LA610S			3,210
DBA-LA700S	WAKE		5,884
DBA-LA710S			1,000
HBD-LA700V	HIJET CADDIE		175
HBD-LA710V			65
5BA-LA800S	MOVE CANBUS		15,807
5BA-LA810S			3,156
DBA-LA400K	COPEN	1,153	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S500P	HIJET TRUCK	2019	8,038
EBD-S510P			19,907
DBA-LA250A	PIXIS JOY		1,869
DBA-LA260A			415
5BA-LA350A	PIXIS EPOCH		2,648
5BA-LA360A			703
DBA-LA700A	PIXIS MEGA		2,234
DBA-LA710A			434
EBD-S500U	PIXIS TRUCK		448
EBD-S510U			968
DBA-LA150F	STELLA		1,252
DBA-LA160F			649
5BA-LA350F	PLEO PLUS		1,155
5BA-LA360F			445
DBA-LA600F	CHIFFON		295
DBA-LA610F			117
EBD-S500J	SAMBAR TRUCK		429
EBD-S510J		1,485	
		TOTAL	147,042