

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5328	DATE	June. 2. 2023
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF3	「N-BOX」 「N-BOX Custom」	2017～2019	200,796
DBA-JH1	「N-WGN」 「N-WGN CUSTOM」		51,976
DBA-JH2			11,902
DBA-JG1			13,654
DBA-JG2	「N-ONE」		2,290
HBD-JJ1	「N-VAN」		2018～2019
DBA-JF1	「N-BOX SLASH」 「N-BOX +」	2017～2019	7,376
DBA-JF2	「N-BOX + Custom」		1,300
DBA-JW5	「S660」		3,480
		TOTAL	307,351