

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5329	DATE	6. Jun. 2023
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the main harness, the waterproof structure of the connector that is connected to the O2 sensor wiring is not appropriate, so water that accumulates in the connector by running in the rain, etc., may be drawn inside the connector as the O2 sensor cools down after the engine is stopped, etc., causing a short circuit to the terminals. As a result, the engine warning lamp will come on, and if the vehicle continues to be used, the exhaust gas may not satisfy the standard values.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8 BL-RN80J	XSR900	2022~2023	1,856
8 BL-RN70J	TRACER900 GT	2021~2023	1,694
8 BL-RN69J	MT-09 MT-09 SP	2021~2023	2,209
TOTAL			5,759