

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5327	DATE	Jun 09, 2023
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	If the wheel loader is kept to operate with filter frozen, engine oil will flow back into the combustion chamber, and engine rotation cause overrotate. The wheel loader will be not stop properly. In the worst case, there is a possibility that engin is damage when keep to operate by overrotate.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-R430E	「R430E」	R430E-10001~R430E-11125 August 5, 2016 to November 29, 2022	991
	「6SDDL8」	R430E-10005~R430E-10331 August 8, 2016 to January 15, 2018	133
YDM-R530E	「R530E」	R530E-10001~R530E-11056 October 6, 2016 to November 25, 2022	1,017
	「6SDDL10」	R530E-10020~R530E-10259 September 29, 2016 to February 15, 2018	14
YDM-R630E	「R630E」	R630E-10001~R630E-10263 August 9, 2016 November 17, 2022	247
	「6SDDL12」	R630E-10004~R630E-10051 September 8, 2016 to September 25, 2017	16
		TOTAL	2418

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.

This case was a recall notification with the notification number "5116" on March 15, 2022, but a cause has been identified, a new notification will be made.