

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 3 5	DATE	Jun. 15. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the engine control computer, it may be erroneously determined that the accelerator pedal sensor is malfunction when a specific accelerator pedal operation is performed due to the inappropriate accelerator diagnosis control program at the time of development and insufficient evaluation of fail-safe control. Therefore, the fail-safe control for stopping the output may be operated and the vehicle may not be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
3DF-CN4E26	N I S S A N C A R A V A N	2 0 2 2	58
3DF-CN8E26			169
3DF-VN2E26			2, 178
3DF-VN6E26			1, 646
3DF-JVN2E26	I S U Z U C O M O		8
		TOTAL	4, 059