VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5343	DATE	.Jun.22 2023	
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation			
DESCRIPTION OF DEFECT	On some heavy-duty trucks with 6R20 engines, the engine harness was improperly assembled, causing the engine harness to make heavy contact with the harness fixing bracket. Therefore, if the bracket contact area of the engine harness is worn and damaged by engine vibration, the engine may stop suddenly, or the engine may not be restarted. In the worst case, fire may occur due to an arc caused by a short circuit at the relevant part.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FS70HZ		2021~2022	211
2KG-FS74HZ		2021~2022	193
2KG-FU70HY		2021 ~ 2022	11
2KG-FU74HZ		2021 ~ 2022	107
2KG-FV70HJR		2017~2022	867
2KG-FV70HX		2018 ~ 2022	1,210
2KG-FV70HY		2021 ~ 2022	166
2KG-FV70HYP		2019 ~ 2022	146
2KG-FV70HZ		2021~2022	140
2KG-FV70HZP		2019 ~ 2022	43
2KG-FV74HJR		2018~2022	92
2PG-FP74HDR		2021 ~ 2022	920
2PG-FP74HER	「FUSO SUPER GREAT」	2021 ~ 2022	351
2PG-FP74HGR		2021 ~ 2022	72
2PG-FS70HZ		2017 ~ 2022	1,123
2PG-FS74HY		2017 ~ 2022	228
2PG-FS74HZ		2017~2022	14,028
2PG-FS75HY		2019 ~ 2021	8
2PG-FS75HZ		2017 ~ 2022	2,097
2PG-FU70HY		2017 ~ 2022	382
2PG-FU74HY		2017 ~ 2022	282
2PG-FU74HZ		2017 ~ 2022	5,484
2PG-FU75HZ		2017 ~ 2022	1,256
2PG-FV70HX		2017~2022	4,279
2PG-FV70HY		2017~2022	1,039
2PG-FV70HZ		2017~2022	1,106
2PG-FV74HJR		2018~2022	88
2PG-FV74HZ		2017 ~ 2022	904
2PG-FY70HY		2017~2022	243
2PG-FY74HY		2017~2022	369
2RG-FP74HDR		2017~2021	2,462

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FP74HER	- 「FUSO SUPER GREAT」	2017~2021	1,069
2RG-FP74HGR		2017~2021	158
		TOTAL	41,134