

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5336	DATE	June.23. 2023
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	On bracket of center bearing where driveshafts for tank truck's load handling pump are joined, there is an area left unwelded following inappropriate welding instructions. Therefore the strength of weld is not sufficient that there could be a case the weld cracks under vibration from driving, or other elements. If the vehicle is kept being operated, the crack may extend and in the worst case the bracket may fall off the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYG60CM	GIGA	2019~2022	6
2KG-CYL60C		2022	5
2KG-CYE60CM		2022	1
2KG-CXG60CT		2020	1
2PG-FVR90U2	FORWARD	2020	1
2PG-FTR90U2		2020	1
2PG-FSR90S2		2020	1
2PG-FN1AJA	HINO PROFIA	2021	6
2PG-FN1AJG		2020~2022	2
2KG-FN1AJA		2019	2
2KG-FN1AJG		2021~2022	2
2PG-FE2ABA	HINO RANGER	2020~2021	2
2PG-FE2ACA		2022	1
2KG-FE2ABA		2021	1
2KG-FK62FZ	FUSO FIGHTER	2020~2022	10
2RG-BSR90S2	CONDOR	2022	2
2PG-CD4CA	QUON	2021	1
		TOTAL	45