

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5337	DATE	June 23, 2023
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In some of the front LED fog lamps, the amount of solder applied to the LED chip was small due to inadequate process control. Therefore, if the lamp is used continuously in this state, the solder may peel off and the lamp may become dark. In the worst case, the lamp may not be turned on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-M900S	THOR	2020-2021	3,242
5BA-M900S			3,573
5BA-M910S			1,113
5BA-M900F	JUSTY		622
5BA-M910F			275
4BA-M900A	ROOMY		15,221
5BA-M900A			24,974
5BA-M910A			6,461
			TOTAL