

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5338	DATE	June 23, 2023
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>Regarding forward recognition cameras for the preventive safety function, the adhesive strength of camera bracket to the windshield glass is weak in some cases due to the improper adhesion process control.</p> <p>Therefore, the bracket with camera may come off from the windshield glass during driving. This may interrupt driver's forward view and may not satisfy the standard in the worst case. Also, the edge shape of camera bracket may not satisfy the standard required.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2019-2020	24,889
DBA-LA160S			4,912
DBA-LA250S	CAST		13,318
DBA-LA260S			2,583
5BA-M700S	Boon		3,678
5BA-M710S			671
DBA-LA150F	STELLA		1,390
DBA-LA160F			722
DBA-LA250A	PIXIS JOY		1,498
DBA-LA260A			318
5BA-M700A	PASSO		16,679
5BA-M710A			3,073
		TOTAL	73,731