

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5339	DATE	Jun.23.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the waterproof cap of back door, due to an improper work instruction, no cap is installed, causing the wire harness to be covered with water coming from high pressure car washing. If the vehicle is continuously operated in this condition, the rust may be generated on the connector terminals, causing the conduction failure, resulting in the license plate lamp, high mount stop lamp and/or door lock inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
4BA-GXPA16	[GR YARIS]	2022-2023	153	GRMN and GRMN circuit package grade
		TOTAL	153	