

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5340	DATE	June.23.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front lower arms of the front suspension, due to improper manufacturing of the ball joint mounting area, there is a possibility that the front lower arm(s) may have cracks. In this condition, if the vehicle is operated repeatedly on an uneven road, the cracks propagate, and in the worst case, the lower arm could separate and ball joint could drop off resulting in a loss of control the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-KSP210	[YARIS]	2019-2023	96,392	
5BA-MXPA10			66,748	
5BA-MXPA15			19,823	
6AA-MXPH10			134,694	
6AA-MXPH15			21,285	
6AA-MXPK10	[AQUA]	2021-2023	6,671	
6AA-MXPK11			132,099	
6AA-MXPK15			720	
6AA-MXPK16			20,356	
5BA-MXPC10G	[SIENTA]	2022-2023	28,077	
5BA-MXPC12G			951	
6AA-MXPL10G			54,665	
6AA-MXPL12G			535	
6AA-MXPL15G			11,124	
		TOTAL	594,140	