

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5324	DATE	10 Jul, 2023
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>① When there was a revision of the safety standards for road vehicles, a turn unit of a direction indicator was incorrectly designed so that a driver is not alerted in the event of a broken wire or other malfunction in the direction indicator. As a result, there is a risk that a driver may continue to drive without noticing that the direction indicator is malfunctioning.</p> <p>② Despite the need to change design of a turn unit of a turn signal when the safety standards for road vehicles were revised, production without making any changes was continued. Therefore, there is no function to warn a driver in the event of a malfunction such as a broken wire in the direction indicator. As a result, there is a risk that a driver may continue to drive without noticing that the direction indicator is malfunctioning.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VS323	「VM221」	2007~2015	18
	「VM221G」	2006~2015	462
	「VM219」	2006~2015	71
	「VM219G」	2006~2015	1084
	「VS323」	2006~2015	1341
	「VS321」	2006~2015	657
VC18B	「VM218」	2007~2015	443
VC23B	「V323」	2015~2020	322
	「V321」	2015~2020	106
	「V220」	2016~2018	3
	「V220G」	2015~2019	194
VC24B	「V324」	2020~2021	172
	「V322」	2020~2021	64
	「V221G」	2020~2021	57
SB-VG60	「VY60」	2006~2008	91
	「VG60」	2006~2008	200
SA-VY50	「VY50」	2006~2008	147

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SA-VY43	「VS38」	2006~2008	165
	「VY43」	2006~2008	337
VM217	「VM217」	2006~2009	44
	「VM217G」	2006~2009	266
	「VM215」	2006~2009	280
	「VM215G」	2006~2009	784
	「VM213」	2006~2008	450
	「VM213G」	2006~2008	138
SB-VG85	「VG85」	2006~2008	113
	「VG585」	2008~2010	100
SB-VR98	「VR98」	2006~2008	167
	「VR698」	2008~2010	85
EDR-VC10C	「VR6108」	2010~2013	119
		TOTAL	8480