

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5353	DATE	Jul.12.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	Due to an improper internal structure of a current rectifying module of a DC-DC converter, if the module fails during the operation, there is a possibility that an electrical short circuit could occurs inside the module. In this condition, the warning lights will illuminate and the current from the auxiliary battery continues to flow through the module generating heat, in the worst case, vehicle fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6LA-AXAP54	[RAV4 PHV]	2020-2022	6,073
6LA-AAZH26	[NX450h+]	2021-2022	1,544
		TOTAL	7,617