

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5355	DATE	July.12.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the experimental or modified vehicles produced as a hydrogen fuel cell vehicle, due to inappropriate design of peripheral parts related to the modification,</p> <p>#1 There is no wiring harness connected to the brake fluid level sensor of the brake device, the brake warning light does not illuminate even if the amount of brake fluid level would below the specified.</p> <p>#2 The front fog lamp indicator light was not installed, the operating status of fog lamp does not display to the driver.</p> <p>#3 The headlamp auto light feature was not equipped, and the auto light does not work.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
2KG-XZB70 ”kai”(modified)	[TOYOTA COASTER]	2020-2021	5	#1 and #2 modified car
		2020	1	#2 modified car
XZB70		2019	1	#2 experimental car
shisaku	—	2021-2022	7	#1 and #3 experimental car
3DA-GDH303W ”kai”(modified)	[GRANACE]	2021	4	#1 and #2 modified car
TOTAL			18	