

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 5 1	DATE	Jul.14.2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the engine room harness, there was a deficiency in the arrangement of the harness due to insufficient verification at the time of development. when the tip of the bolt for fixing the engine control unit is located in the slit part of the harness protection material, it enters the inside of the harness protection material and is in direct contact with the electric wire. Therefore, if the vehicle is continued to be used, the electric wire covering will be damaged, the tip of the bolt will come into contact with the core wire, resulting in a short circuit, and in the worst case, the motor may stop during the driving and the vehicle may not be driven.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HC27	SERENA	2018~2021	17,700
6AA-HC27			
DAA-HFC27		2017~2021	109,100
6AA-HFC27			
		TOTAL	126,800