

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5359	DATE	July 26, 2023
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Rainwater etc. may enter the parking brake valve of shovel loaders through the gap of the lead wire insertion portion due to insufficient consideration of entry of rainwater etc. into the parking brake valve. If the machine is used as it is, the inside of the solenoid may rust and the force to keep the parking brake released may decrease, and in the worst case the parking brake may operate during travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-WA121	WA320-7	2016-2017	171
YDR-WA135	WA320-8	2017-2023	555
TOTAL			726