

**VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN
JAPAN**

Domestic Vehicles

CAMPAIGN No.	5356	DATE	July 27, 2023
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Some camshafts of the engines have insufficient surface hardness because the heat treatment of the exhaust cam is inappropriate due to a program setting error of the heat treatment machine. Therefore, abnormal wear of the exhaust cam may occur, causing abnormal noise, and if the vehicle is used continuously, the engine may stop and cannot be restarted.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SUZUKI	GIXXER	2022	104
		TOTAL	104