## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5360	DATE	July. 27. 2023		
MANUFACTURER	HONDA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	Due to its inappropriate control program, the engine control unit (ECU) may incorrectly recognize the instantaneous reverse rotation of the crank shaft as an error while controlling the position to stop the engine when the vehicle is running on electricity or regenerating, and reset to delete the malfunction diagnosis information. For this reason, it is not compliant with the standards specified in Article 31 of the Safety Standards (Attachment 48 to the Detailed Notice "Technical standards for on-board diagnosis systems.")				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
6AA-FL4	「CIVIC」	2022~2023		3,765
6AA-RZ4		20	00	1,813
6AA-RZ6	「ZR-V」	2022		364
			TOTAL	5,942