## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5362	DATE	Aug. 7. 2023	
MANUFACTURER	Hino Motors, Ltd.			
DESCRIPTION OF DEFECT	On certain heavy-duty hybrid route buses, due to the improper hybrid control program, the sliding part of the supply pump may wear because the lubrication can become poor due to foreign substances in the fuel when the engine is started. Therefore, if it is continued to be used under the condition, the pump may be damaged, causing the vehicle to unable to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2SG-HL2ANBP	[HINO Blue Ribbon Hybrid]	2017~2023	272
2SG-HL2ASBP		2017~2023	67
		TOTAL	339