

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5363	DATE	August 7 ,2023
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain heavy-duty hybrid route buses, due to the improper hybrid control program, the sliding part of the supply pump may wear because the lubrication can become poor due to foreign substances in the fuel when the engine is started. Therefore, if it is continued to be used under the condition, the pump may be damaged, causing the vehicle to unable to drive.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2SG-HL2ANBD	[ISUZU ERGA]	2018-2023	29
2SG-HL2ASBD		2018-2019	7
		TOTAL	36