

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5368	D A T E	Aug.31. 2023
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In rear combination lamps, due to insufficient electronic circuit settings of the components, it may be difficult to raise the voltage to turn on the rear turn signals and rear vehicular hazard warning signals. This may cause the rear turn signals and rear vehicular hazard warning signals to temporarily inoperable.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-ZD8	「BRZ」	2021～2022	5,498
3BA-ZN8	「GR86」	2021～2022	7,577
		TOTAL	13,075