

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5373	DATE	2023/9/15
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	In a rotary snowplow, the fuse capacity connected to the secondary side is larger than the contact capacity of the key switch, and the contact of the key switch may be damaged before the fuse blows, preventing the engine from starting.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	NR30P	2004~2012	154
-	NR31P	2012~2018	101
		TOTAL	255