

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5378	DATE	Sep. 21. 2023
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Some of the bolts that fasten the drive plate and torque converter in the CVT (continuously variable transmission) may have been improperly tightened.</p> <p>Therefore, those bolts may come loose and drop into the torque converter housing causing the abnormal noise, if the vehicle is continuously used with the above condition.</p> <p>In the worst case, the dropped bolt may be caught between the drive plate and the torque converter housing, resulting in the engine stalling and impossibility of re-starting.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5AA-MK53S	SPACIA	2023	2	
4AA-MK53S			2	
		TOTAL	4	