## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

	Domestic Vehicles				
CAMPAIGN No	5386		DATE	October-5-2023	
MANUFACTURER	PABCO CO .,LTD				
DESCRIPTION OF DEFECT	Regarding the tail lamp located at the lower rear of the HDT WING vehicle, the distance from the outermost side of the vehicle to the tail lamp exceeds the criteria due to insufficient consideration during design. Therefore, the safety standard of the mounting position of the tail lamp is not satisfied.				
TYPE	COMMERCIA	L NAME		ODEL /EAR CALLED	NUMBER OF VEHICLE
2PG-CG5CA	UD TRUCKS QUON			2022	3
2RG-CG5FA				2022	1
			Т	OTAL	4