

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5389	DATE	Oct.18.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the rear seat belt assemblies, due to improper manufacturing control of the parts in the seat belt retractors, there is possibility that an incorrect specification shaft was assembled with the seat belt retractors. In this condition, when the force limiter is activated in the event of a crash, the seat belt extended further than intended, which does not comply with Protection of the occupants performance in Safety Regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-MXPK10	[AQUA]	2023	710
6AA-MXPK11			11,934
6AA-MXPK15			97
6AA-MXPK16			1,926
		TOTAL	14,667

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Seatbelt RH	73360-52520	2023	3	[AQUA]
Seatbelt LH	73370-52510		3	
		TOTAL	6	