

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5390	DATE	Oct.18.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the subject high-pressure fuel pumps, due to insufficient design studies, the necessary strength may be insufficient after press-fit assembly of components, and the inside of the pump may be worn or damaged during the use process. Therefore, stress is concentrated in the pump weld, and cracks may occur and lead to fuel leakage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-NRE210	[COROLLA]	2019-2022	673
3BA-NRE210H	[COROLLA SPORT]	2018-2022	17,131
3BA-NRE214H		2018-2022	4,807
3BA-NRE210W	[COROLLA TOURING]	2019-2022	1,685
3BA-NGX10	[C-HR]	2019-2023	6,049
3BA-NGX50		2020-2023	3,054
TOTAL			33,399