VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5387	DATE	October 19 ,2023
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		In this defect relating to the light-duty trucks shown below, each equipped with a freezer unit as its rear body, the structure of where the idle pully for the belt driving the freezer unit's compressor is fitted on the cylinder block with a fastening bolt is inappropriate, so that in some of the said trucks, the fastening bolt receives excessive stress due to belt tension and thus breaks down, possibly causing the belt to come off and resulting in the freezer unit malfunctioning and, in the worst case, the pully falling on the road while the trucks are running.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2RG-NPR88AN kai	[ELF]	2020	1
		TOTAL	1