VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5388	DATE	0ct. 24. 2023	
MANUFACTURER	Trantechs, Ltd.			
DESCRIPTION OF DEFECT	In the mounting brackets for the refrigerator condenser which is installed between the wheel base of large refrigerator trucks, cracks may occur in the fasteners due to insufficient design consideration. As a result cracks develop due to vibration during operation and the mounting brackets can break. In the worst case the refrigerator condenser may fall off, interfering with other traffic.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-FW1EXEG	HINO Profia	2016~2017	25
		TOTAL	25