VEHICLE SAFETY/POLLUTION RECALL CAMPAING IN JAPAN



CAMPAIGN No.	5399	DATE	0ct.25.2023	
MANUFACTURER	Hino Engineering Annex Co., Ltd			
DESCRIPTION OF DEFECT	For large trucks with modified trunnion suspension to lower the floor, Due to inappropriate instructions for processing the trunnion spacer, a gap may occur between the trunnion seat and trunnion spacer during assembly Therefore, as the trunnion spacer wears down due to running vibration, the gap decreases, the axial force of the U-bolt that fixes the leaf spring decreases, the shock absorber may not function properly.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
2DG-FR1AHA	[HINO PROFIA]	2018~2019	2
2DG-FS1EHA		2019~2022	21
	15444	TOTAL	23