VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN Domestic Vehicl

			Domestic Vehicles		
CAMPAIGN No.	5392	D A T E	Oct.26. 2023		
MANUFACTURER	SUBARU CORPORATION				
DESCRIPTION OF DEFECT	The bolt attaching water pipe to the engine may have been insufficiently tightened during engine assembly process. If the vehicle continues to be operated in this condition, the insufficiently tightened bolt could come off and coolant could leak. In the worst case, coolant could come in contact with exhaust pipe, potentially leading to a fire.				

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
4BA-VN5	「LEVORG」	2023		2
4BA-SK5	「FORESTER」	2023		9
4BA-BT5	「LEGACY」	2023		1
		<u>.</u>	TOTAL	12