VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 3 9 6	DATE	0ct. 26. 2023	
MANUFACTURER	NISSAN			
DESCRIPTION OF DEFECT	In the screws for fixing the front bumper clip fastened to the left headlamp, they are not fastened correctly, and rattling may occur in the front bumper due to the inappropriate torque settings of the fastening tool used for assembly. Therefore, the pedestrian collision detection sensor fixed to the front bumper may not operate normally at the time of collision with the pedestrian, the pop-up hood may not operate normally, and in the worst case, the pedestrian head and leg protection standards may not be satisfied at the time of collision with the pedestrian.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
3 B A – R Z 3 4 5 B A – R Z 3 4	FAIRLADY Z	2022~2023	4 7 6
		TOTAL	4 7 6