

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5404	DATE	Nov.2.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the fuel pump impeller, due to an improper injection molding process, the resin density of some impellers may be low and they deform by absorption of excessive fuel. If this were to occur, the impeller may interfere with the fuel pump body and fuel pump becomes inoperative, and in the worst case, resulting in engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR80W	[NOAH] [VOXY]	2017-2019	86,019
DBA-ZRR80W “Kai”(modified)			
DBA-ZRR85W			17,897
DAA-ZWR80W		2018-2019	12,190
DBA-ZRR80G	[NOAH] [VOXY] [ESQUIRE]	2017-2019	46,120
DBA-ZRR80G “Kai”(modified)			
DBA-ZRR85G			14,409
DBA-ZRR85G “Kai”(modified)			
DAA-ZWR80G		2018-2019	13,835
CBF-TRH200V	[HIACE] [REGIUS ACE]	2017-2019	31,557
CBF-TRH200K			
CBF-TRH200K “Kai”(modified)			
CBF-TRH211K			1,014

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-TRH216K	[HIACE] [REGIUS ACE]	2017-2019	1,489
CBF-TRH221K			1,070
CBF-TRH226K			1,097
CBF-TRH223B			1,076
CBF-TRH223B “Kai”(modified)			
CBF-TRH228B			968
CBF-TRH228B “Kai”(modified)			
CBA-TRH214W	[HIACE]	2017-2019	5,569
CBA-TRH214W “Kai”(modified)			3,816
CBA-TRH219W			
CBA-TRH219W “Kai”(modified)			
CBA-TRH224W			1,716
CBA-TRH229W			1,444
DBA-AGH30W	[ALPHARD] [VELLFIRE]	2018-2019	22,657
DBA-AGH35W		2017-2019	5,774
DAA-AYH30W		2018-2019	14,397
CBA-TRJ150W	[LAND CRUISER PRADO]	2017-2019	13,625
DBA-GRS210	[CROWN]	2017-2018	824
DBA-GRS211			277
DAA-AWS210			9,303
DAA-AWS211			1,491
DAA-AWS215			198

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ASU60W	[HARRIER]	2018-2019	796
DBA-ASU65W			581
CBA-URJ202W	[LAND CRUISER]	2018-2019	720
CBF-TRH221S	[TOYOTA AMBULANCE]	2017-2019	46
CBF-TRH226S			629
DBA-GRS210	[CROWN PATROL CAR]	2017-2018	359
DBA-GRS211			52
6AA-UWG60	[CENTURY]	2018	51
DBA-AGZ10	[NX300]	2018-2020	4,205
DBA-AGZ15		2019	949
DAA-AVE30	[IS300h]	2017-2019	3,205
DAA-AVE35			492
DBA-AGL20W	[RX300]	2018-2020	2,016
DBA-AGL25W			719
DAA-AWL10	[GS300h]	2017-2019	1,697
DAA-GWL10	[GS450h]	2018-2019	348
DAA-AVC10	[RC300h]	2017-2019	1,060
DBA-URJ201W	[LX570]	2018-2019	343
CBF-TRH200M	[BONGO BRAUNY VAN]	2019	8
		TOTAL	328,108

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR80W	[NOAH] [VOXY]	2014-2020	94
DBA-ZRR80W “Kai”(modified)			
DBA-ZRR85W		2014-2017	37
DBA-ZRR80G	[NOAH] [VOXY] [ESQUIRE]	2014-2017	57
DBA-ZRR80G “Kai”(modified)			
DBA-ZRR85G			
DBA-ZRR85G “Kai”(modified)			
DBA-ARS210	[CROWN]	2015-2016	10
DBA-GRS210		2013-2014	9
DBA-GRS211			5
DAA-AWS210		2013-2016	37
DAA-AWS211		2014	1
DAA-AWS215		2015	1
6AA-AZSH20		2018-2019	3
DAA-GWS214		2015, 2017	2
DBA-URS206		[CROWN MAJESTA]	2009-2012
DBA-AGH30W	[ALPHARD] [VELLFIRE]	2015-2019	39
DBA-AGH35W		2015-2018	9
DBA-GGH30W		2015-2019	11
DBA-GGH35W			7
DAA-AYH30W		2019	1

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBF-TRH200V	[HIACE] [REGIUS ACE]	2014-2019	18
CBF-TRH211K		2016, 2017	2
CBF-TRH221K		2016	1
CBA-TRH214W	[HIACE]	2015-2017	7
CBA-TRH214W “Kai”(modified)			
CBA-TRH219W “Kai”(modified)		2014	1
CBA-TRH224W		2016	2
CBA-TRH229W		2015, 2016	2
DBA-KGC30	[PASSO]	2012-2015	18
DBA-KGC35		2012-2016	4
DBA-NGC30		2014, 2015	2
CBA-GSJ15W	[FJ CRUISER]	2011-2018	18
DAA-AXVH70	[CAMRY]	2017-2019	15
CBA-URJ202W	[LAND CRUISER]	2011-2016	9
CBA-UZJ200W		2008	4
CBA-QNC20	[bB]	2013	1
CBA-QNC21		2013-2015	6
DBA-GRS210	[CROWN PATROL CAR]	2016-2017	5
CBA-GRJ150W	[LAND CRUISER PRADO]	2009	1
CBA-GRJ151W		2009-2012	3
CBF-TRH226S	[TOYOTA AMBULANCE]	2014-2016	3

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-USF40	[LS460]	2006-2017	84
DBA-USF45		2012-2013	3
DBA-USF41	[LS460L]	2013, 2015	2
DBA-VXFA50	[LS500]	2019	1
DAA-UVF45	[LS600h]	2011-2015	20
DAA-UVF46	[LS600hL]	2012-2015	9
DBA-AGL20W	[RX200t]	2016-2017	4
DBA-AGL25W	[RX200t] [RX300]	2016, 2018	2
DAA-GYL20W	[RX450h]	2015-2017	12
DAA-GYL25W		2015-2019	25
DBA-ARL10	[GS200t]	2016	1
DBA-GRL11	[GS250]	2012-2016	8
DBA-GRL10	[GS350]	2012-2015	8
DBA-GRL12		2016	1
DBA-GRL15		2012-2015	3
DAA-GWL10	[GS450h]	2012-2016	5
DBA-URS190	[GS460]	2007	1
DAA-AWL10	[GS300h]	2014-2017	5
DBA-ASE30	[IS200t]	2015-2016	4
DBA-GSE30	[IS250]	2013-2015	4
DBA-GSE31	[IS350]	2013-2015	3
DBA-USE20	[IS F]	2009	1

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-AVE30	[IS300h]	2013-2016	3
DBA-URZ100	[LC500]	2017	9
DAA-GWZ100	[LC500h]	2017	3
DBA-GSC10	[RC350]	2015	1
DAA-AVC10	[RC300h]	2016	1
DBA-URJ201W	[LX570]	2017	1
TOTAL			703

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Fuel pump	23220-75241	2017-2019	418	[TOYOTA AMBULANCE]
	23220-75221		32	[TOYOTA AMBULANCE] [HIACE] [REGIUS ACE]
	23220-37221		98	[NOAH] [VOXY]
	23220-37200		21	[ESQUIRE]
	23220-36070		48	[CROWN]
	23220-31480		48	[CROWN] [CROWN PATROL CAR] [IS250] [IS300h]

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Fuel pump	23221-31130	2017-2019	13	[ALPHARD] [VELLFIRE] [CROWN] [GS200t] [GS300] [GS350] [IS200t] [IS300] [IS350] [LC500] [LC500h] [LS500] [LS500h] [RC200t] [RC300] [RC350] [RX450h] [RX450hL]
	23220-36150		16	[ALPHARD] [VELLFIRE]
	23220-36121		6	
	23220-36040		8	[GS300h] [IS300h] [RC300h]
	23220-75171		2	[LAND CRUISER PRADO]
	23221-36030		214	[HARRIER] [NX200t] [NX300] [RX200t] [RX300]
	23220-38030		114	[GS250] [LS460] [LS460L]

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Fuel pump	23220-38041	2017-2019	54	[CROWN] [CROWN MAJESTA] [IS350] [IS F] [RC350] [GS350] [GS450h] [GS460] [LS600h] [LS600hL]
	23220-38050		23	[CENTURY] [LS600h] [LS600hL]
	23220-25030		1	[CROWN]
	23221-25030		18	[CAMRY] [ES300h]
	23220-31430		13	[LAND CRUISER PRADO] [FJ CRUISER]
	23220-50271		10	[LAND CRUISER] [LX570]
	23220-50261		1	[LAND CRUISER]
	Fuel suction tube ASSY (Fuel pump module ASSY)		77020-58040	22
77020-58051		20		
77020-58031		18		
77020-58030		14		
77020-58050		14		
77020-58060		4		
77020-58070		5		

The affected parts shipped as repair parts, and could not possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE	
Fuel suction tube ASSY (Fuel pump module ASSY)	77020-60610	2017-2019	5	[LAND CRUISER PRADO]	
	77020-60640		2		
	77020-48271		2	[RX450h] [RX450hL]	
	77020-60362		21	[LAND CRUISER]	
	77020-60352		12		
	77020-60540		11	[LAND CRUISER] [LX570]	
	77020-60411		14	[LAND CRUISER PRADO]	
	77020-30342		14	[CROWN MAJESTA] [GS460]	
	77020-35181		8	[FJ CRUISER]	
	77020-33510		11	[CAMRY] [ES300h]	
	77020-53131		4	[IS F]	
	23210-B1100		2017-2021	25	[bB]
	23100-B1080			24	[PASSO]
		TOTAL	1,408		