

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5400	D A T E	Nov.9. 2023
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the manufacturing process for the inhibitor switch intended to detect shift position, due to inappropriate welding jig replacement standard, the switch may have been insufficiently welded, resulting in insufficient seal. If the vehicle continues to be operated in this condition, moisture may enter the switch, resulting in poor electrical conductivity, which may lead to engine no start or backup lamps not illuminating.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-VN5	「LEVORG」	2021	9,645
4BA-SK5	「FORESTER」	2021	3,423
		TOTAL	13,068

Vehicles that may have been assembled with the parts shipped as replacement repair parts

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4BA-VN5	「LEVORG」	2020~2021	5
4BA-SK5	「FORESTER」	2021	1
		TOTAL	6